

HAKKO FR-803B

訂正表 / 修正表 / Correction sheet

この度は白光製品をお買い求めいただき、ありがとうございます。
本製品で一部訂正がありましたことを以下にお知らせします。
謝辞、這次請購買HAKKO 產品。對以下告知本產品有一部分修正。

Thank you for purchasing the HAKKO products.
Please note that the cautionary note is corrected as follows.

P22

- 誤) No. A1124B シングル ϕ 2.5 はハッコーFR-803Bには使用しないでください。
ハッコーFR-803Bで使用した場合、熱風の吹き出し口を塞ぐため危険です。
- 正) 旧パーツであるNo. A1124 シングル ϕ 2.5 及びNo. A1142 シングルマガリ ϕ 1.5×3
はハッコーFR-803Bには使用しないでください。ハッコーFR-803Bで使用した場合、
熱風の吹き出し口を塞ぐため危険です。

P22)

- 誤) No. A1124B 單獨式 ϕ 2.5 及No. A1142B 彎曲單管 1.5×3 不能用於 HAKKO
FR-803B。如果用於HAKKO FR-803B, 會因熱風吹出口被堵塞而發生危險。
- 正) 舊部件的No. A1124 單獨式 ϕ 2.5 及No. A1142 彎曲單管 1.5×3 不能用於 HAKKO
FR-803B。如果用於HAKKO FR-803B, 會因熱風吹出口被堵塞而發生危險。

P22)

Wrong)

Do not use No. A1124B Single ϕ 2.5 (0.09) and No. A1142B Bent Single 1.5 × 3
(0.06 × 0.12) nozzle with the HAKKO FR-803B. These nozzles do not have space
to blow hot air, using them with the HAKKO FR-803B may result in danger.

Correct)

Do not use the old part numbers A1124 Single ϕ 2.5 (0.09) and A1142 Bent Single
1.5 × 3 (0.06 × 0.12) nozzle with the HAKKO FR-803B. These nozzles do not have
space to blow hot air, using them with the HAKKO FR-803B may result in danger.